

TM-T20II (**7 model) Firmware Updater

Version	Ver.10.25 ESC/POS
Uploaded date	2020/3/9 9:00
File size	20,960KB
Explanation	<p>This software updates the TM-T20II(**7 model) Firmware to Version 10.25 ESC/POS. Depending on the usage environment, firmware update might cause faulty printer operations. Before updating the firmware, please confirm with the printer seller or SI and others if there is no problem to update it.</p> <p>[Changes from previous version] Firmware Change History</p> <p>[Support Model] TM-T20II (**7 model)</p> <p>[Support OS] - Windows 10 (32/64bit) - Windows 8.1 (32/64bit) - Windows 8 (32/64bit)</p> <p>[Notes] This firmware updater can be used only for TM-T20II **7 model.</p>

Firmware Change History for TM-T20II (**7 model)

Version	Category	Detail
10.10 ESC/POS	-	New Release
10.20 ESC/POS	Added new function	Support of Flash ROM W25Q64JVSSIM made by Winbond.
	Bug fix	Fixed a problem in data reception flow control during USB communication.
		Fixed a problem that gateway address becomes "0.0.0.0" when LAN cable is removed / connected.
		Fixed a problem that Wi-Fi connection may not be possible when Wi-Fi security setting is set to enterprise.
		Fixed a problem that the firmware update fails rarely.
10.21 ESC/POS	Added new function	Added standby mode setting item on EpsonNet Config Web version.
	Bug fix	Fixed a problem that network communication may become impossible when the link state of the network changed.
		Fixed a problem that network communication may become impossible when returning from the standby state.
10.22 ESC/POS	Added new function	Added setting item of "Wellknown Community Name" on EpsonNet Config Web version.
	Changed function	NOT support TLS1.0/1.1 for HTTPs, in case of "Encryption Strength" setting is set to "High".
		Changed to process ENPC 03-0021 during power saving.
	Bug fix	Fixed Vulnerability of WPA2(OT-WL02)
		Fixed Port 9100 connection may become impossible.
		Fixed LPR printing stops halfway.
		Fixed LPR printing may be delayed.
10.24 ESC/POS	Bug fix	Fixed a bug that the printer error may occur after a specific Android tablet which is connected by USB restarted.
		Fixed a bug that cannot print after a timeout occurred in the ePOS-Print.
10.25 ESC/POS	Bug fix	Fixed a minor bug.