

EPSON OPOS ADK

Version	Ver.2.80E R17
Uploaded date	2022/12/5 9:00
File size	31,850KB
Explanation	<p>1.Note</p> <ul style="list-style-type: none">- If you need the Korean version, please use “EPSON OPOS ADK for Korea”. <p>2.Environment</p> <p>[Support OS]</p> <ul style="list-style-type: none">- Windows 10 (32/64bit) -> Windows 10 Pro, Windows 10 Enterprise- Windows 8.1 (32/64bit) -> Windows 8.1, Windows 8.1 Pro, Windows 8.1 Enterprise- Windows 8 (32/64bit) -> Windows8, Windows8 Pro, Windows8 Enterprise- Windows 7 SP1 (32/64 bit) -> Professional, Ultimate, Enterprise- Windows Vista SP2 (32/64 bit) -> Business, Ultimate, Enterprise- Windows XP SP3 (32 bit) -> Professional- Windows 2000 SP4 -> Professional- Windows Server 2012 R2 -> Standard, Essentials, Datacenter- Windows Server 2012 -> Standard, Essentials, Datacenter- Windows Server 2008 R2 SP1 -> Standard, Essentials, Datacenter- Windows Server 2008 SP2 (32/64 bit) -> Standard, Essentials, Datacenter- Windows Embedded Standard 7 *1- Windows Embedded POS Ready 7 32/64 bit- Windows Embedded Standard 2009 (Full component)- Windows Embedded POS Ready 2009- Windows Embedded for Point of Service <p>[Support interface]</p> <ul style="list-style-type: none">- Serial(COM1 - COM4) (COM5 - COM10 can be used by using an extension board)- Parallel: LPT1 - LPT3 (Only operation using onboard port of PC is confirmed)- USB: 1 - 127- Wired/Wireless LAN: No limitations- Bluetooth: COMx (COMx can be used by using a TM Bluetooth Connector Utility. When repairing is done, it is necessary to set the port again.) <p>[Development environment]</p> <ul style="list-style-type: none">- Microsoft Visual Basic 5.0 or later (English edition)- Microsoft Visual C++ 5.0 or later (English edition) <p>[Other requirements]</p> <ul style="list-style-type: none">- *1 There is a need to introduce the following components necessary for operation of the driver. <p>[MUST components]</p> <ul style="list-style-type: none">- Volume Shadow Copy Service : For printer driver Installation- System Restore Core : For printer driver Installation- OLE Dialog Interfaces : For printer driver Installation- Task Scheduler : For USB driver Installation- Primitive: DbgHelp : For USB driver Installation- Local Printing Support : For using a printer driver <p>[Necessary components for each case]</p> <ul style="list-style-type: none">- Communications Port: For using a printer driver, it is necessary to install this port manually if there is no serial or parallel port on a PC.- Primitive: Winhlp32: In case of using a help file of this driver.

* Please resolve dependency after these components are added.

Windows 95/98/NT and 64-bit version of Windows XP are not supported.

3.Supported Products

[Support Model]

- Please read the following "Support Models List.pdf" file.

Support Models List.pdf

4.Changes from the Current Version

[Bug fix]

- Fixed an issue where sometimes continue the Offline error on the asynchronous printing after recovering from a communication outage.
- Fixed an issue where data after "e" was not printed when the barcode containing "e" was printed using the escape sequence [ESC | [*] # R].

EPSON OPOS ADK

Model	Ver. 2.80E R17
Line Display	
DM-D110	Yes
DM-D120	Yes(Vista No)
DM-D210	Yes
DM-D30	Yes
DM-D500	Yes
HardTotals	
IR-700	Yes(Vista No)
SR-610	Yes(Vista No)
Printer	
TM-H5000II	Yes
TM-H5200	Yes
TM-H2000	Yes
TM-H6000II	Yes
TM-H6000III	Yes
TM-H6000IV	Yes
TM-J2000/J2100	Yes
TM-J7000/J7100	Yes
TM-J7500/J7600	Yes
TM-m10	Yes
TM-m30	Yes
TM-T20	Yes
TM-T20II	Yes
TM-T70	Yes
TM-T70II	Yes
TM-T81	Yes
TM-T81II (Simplified Chinese/Vietnam)	Yes
TM-T82 (Simplified Chinese/South Asia)	Yes
TM-T82 (Traditional Chinese)	Yes
TM-T82II	Yes
TM-T88III	Yes
TM-T88III X	Yes(Vista No)
TM-T88IV	Yes
TM-T88IV ReStick	Yes
TM-T88V	Yes
TM-T88VI	Yes
TM-T88VI-iHUB	Yes
TM-T90	Yes
TM-P20	Yes
TM-P60	Yes
TM-P60 Peeler	Yes
TM-P60II	Yes
TM-P60II Peeler	Yes
TM-P80	Yes
TM-P80 Auto Cutter	Yes
TM-L60II	Yes
TM-L90	Yes
TM-L90 Peeler	Yes
TM-L90 LinerFree	Yes
TM-U120	Yes
TM-U120II	Yes
TM-U220A	Yes
TM-U220B	Yes
TM-U220D	Yes
TM-U230	Yes
TM-U325	Yes
TM-U330	Yes
TM-U375	Yes
TM-U675	Yes
TM-U950	Yes
RP-U420	Yes
TM-U295	Yes
TM-U590	Yes

There are models that are not handled in the region.