
CW-C8000 series Firmware Updater

Version	08.62. SJ17P3
Uploaded date	2025/04/08
File size	32,646KB

Explanation

1. Supported Product

- CW-C8000 series

2. Modification in details

No.	Category	Detail
1	Function change	Erased the automatic nozzle checking process performed before printing a nozzle check pattern.
2	Bug fix	Fixed a clogged nozzle (faulty print) that was caused by executing the incorrect micro-vibrating timing to the print head during auto cleaning.
3	Bug fix	Fixed an issue where the internal pressure of the pump cap was not exposed to the atmosphere after the ink accumulated by cleaning in the pump cap.

* For details on the previous changes, refer to "Firmware Change History for CW-C8000 Series."

3. Environment

Software / Package name	FWCL02TL_SJ17P3_Win.zip
OS	Windows11
	Windows 10 (32/64bit)
	Windows 8.1 (32/64bit)
	Windows Server 2022
	Windows Server 2019
	Windows Server 2016
	Windows Server 2012_R2
	Windows Server 2012
I/F	USB3.0
	Wired/Wireless LAN
Other requirements	Administrator account is required.

4. Note / Restriction

Note

The software will update the printer's firmware.

Depending on the usage environment, updating the firmware might cause a malfunction of the printer.

Before updating the firmware, please confirm with the printer seller or SI and others if there is

no problem with updating it.

[Caution]

The updater has the downgrade protection function which prevents the firmware to downgrade to Ver. 08.62.SJ28P1 or earlier.

Use the firmware in combination with the latest printer driver.

Restriction

No.	Detail
1	-

Firmware Change History for CW-C8000 Series

Version	Category	Detail
08.57.SJ0805	Updated support model/OS	New release
08.61.SJ3105	New function	Label management system (Loftware Cloud) from Loftware is supported.
08.61.SJ180A	Bug fix	Fixed an issue that occurred in Roll drive shaft when "Cut (after printing last page)" was selected in Settings For Paper Handling After Print.
		Fixed an issue that occurred in upgrading the firmware after text printing.
08.62. SJ28P1	New function	EPSON Cloud Solution PORT Added the silent installation mode.
	Function change	The update timing for effective nozzles has been optimized.
	Bug fix	Corrected the information displayed on the panel (French) while updating the firmware.
		Hide the unsupported items below: <ul style="list-style-type: none"> - WebConfig: [Waiting time for data reception] - Epson Device Admin: [Suction fan for the label]
		Loftware Cloud Fixed a bug where the incorrect screen appeared when the network communication error occurred.
		Fixed a bug to ensure that restart the printer automatically without performing a power cycle when the Wi-Fi was disconnected.
		EPSON Cloud Solution PORT Calculate methods have been changed for [Length of the media consumed].
08.62.SJ17P3	Function change	Erased the automatic nozzle checking process performed before printing a nozzle check pattern.
	Bug fix	Fixed a clogged nozzle (faulty print) that was caused by executing the incorrect micro-vibrating timing to the print head during auto cleaning.
		Fixed an issue where the internal pressure of the pump cap was not exposed to the atmosphere after the ink accumulated by cleaning in the pump cap.