



TM-T20III (Ethernet models) Firmware Updater

Version	Ver. 20.06 ESC/POS
Uploaded date	16 April, 2025
File size	23,940 KB
Explanation	<p>1. Note The software will update the printer's firmware. Printers for the EEB regions: It cannot be downgraded to Ver. 20.05 or earlier after the firmware is upgraded to ver. 20.06. Depending on the usage environment, updating the firmware might cause faulty printer operations. Before updating the firmware, please confirm with the printer seller or SI and others if there is no problem with updating it.</p> <p>2. Environment [Supported OS] - Windows 11 - Windows 10 (32/64 bit) [Supported interface] - USB 2.0/3.0 - Wired LAN [Other requirements] - An administrator account is required.</p> <p>3. Supported Products [Supported Model] - TM-T20III (Ethernet models)</p> <p>4. Changes from the Current Version [New Function] - Refer to the following Firmware change history. [For Android / iOS operating systems] Use the Firmware Update function of the TM Utility to update the printer's firmware.</p>
	<p>Download the Epson TM Utility</p> <div></div> <p>This application can be downloaded from App Store and Google Play store.</p>

Firmware Change History for TM-T20III (Ethernet models)

Version	Category	Detail
20.02 ESC/POS	-	New Release
20.03 ESC/POS	Changed function	Added models for the OT-WL06.
		Changed default password for WebConfig access from "epson" to the serial number of the printer to comply with the regulations (Chapter 886) in California, U.S.
		Changed contents of the self-signed certificate to comply with the iOS 13 specifications
	Bug fix	Fix a bug that this product cannot print by ePOS-Print when using this product as a network printer from an intelligent printer (like a TM-T88VI-iUIB)
20.04 ESC/POS	Changed function	Added SKU for the OT-WL06.
		Improved a connectivity to AP (SSID is in stealth mode) with W53/W56 when using OT-WL06.
		Changed the SNMP packet processing during the power saving mode.
	Bug fix	Fixed a bug that a recovery point cannot be restored with the "Restore&Delete" operation.
		Fixed a problem that the position is shifted from the middle of the image with ePOS Print.
		Fixed a problem that the network response time slows down when a large amount of UDP packets is received at startup.
20.05 ESC/POS	Update of Support Model/OS	Added support for Windows 11.
		End of support for Windows 8 and Windows 8.1.
	New function	The models have complied with the UK's PSTI bill.
		Added a function in ePOS-Print to support the change in specifications (change in the initial setting value) of Private Network Access starting with Chrome 105.
	Bug fix	*The following problems occur only when SNMP packets that are not supported by the printer are sent periodically. Fixed a bug that caused processing to stop during the transition to power-saving mode, making the printer unable to communicate and print.
20.06 ESC/POS	New Function	Measures to make the device non-subject to the European Radio Equipment Directive (RED).

* QR code is a registered trademark of DENSO WAVE INCORPORATED.