

CW-C4000 series Firmware Updater

| | |
|---------------|---|
| Version | 06.46.TG20P2 |
| Uploaded date | 2025/05/13 |
| File size | 39,902KB |
| Explanation | <p>1.Note</p> <p>The software will update the printer's firmware. Depending on the usage environment, updating the firmware might cause a malfunction of the printer. Before updating the firmware, please confirm with the printer seller or SI and others if there is no problem with updating it.</p> <p>[Caution] The updater has the downgrade protection function which prevents the firmware to downgrade to Ver. 06.44.TG03OA or earlier.</p> <p>2.Environment</p> <p>[Software / Package name] - FWCK03TL_TG20P2_Win.zip</p> <p>[Support OS] - Windows 11 - Windows 10 (32/64 bit) - Windows 8.1 (32/64bit) - Windows Server 2025 - Windows Server 2022 - Windows Server 2019 - Windows Server 2016 - Windows Server 2012 R2 - Windows Server 2012</p> <p>[Support interface] - USB2.0 - Wired/Wireless LAN</p> <p>[Other requirements] - Administrator account is required.</p> <p>3.Supported Products</p> <p>[Support Model] - CW-C4000 Series * See "CW-C4000 Series Technical Reference Guide" for information on how to check the firmware version.</p> <p>4.Changes from the Current Version</p> <ul style="list-style-type: none">- Added support for Windows Server 2025.- [EPSON Cloud Solution PORT]Added the silent installation mode that executes the installation via WebConfig.- The color correction method of ICM has been changed when using texture paper or plain paper.- Released the restriction of the ^FH command for multi-byte text print.]- Released the restriction for drawing figures in low resolution.- Supported Enable/disable setting for TLS1.0/1.1.- Fixed an issue with a missing count when replacing the new maintenance boxes.- Fixed an issue where the black ink density became high when matte ink was used.- Fixed an issue where Automatic restart could not be performed when the Wi-Fi was disconnected.- Fixed an issue that occurred a system error when a status sheet was printed from the operation panel. |

| | |
|--|-----------------------|
| | 5.Restrictions |
|--|-----------------------|

-

Firmware Change History for CW-C4000 Series

| Version | Category | Detail |
|--------------|--------------------------|--|
| 06.27.TG10M2 | Updated support model/OS | New release |
| 06.28.TG26M5 | Function change | Changed the message for Media size error (on the operation panel of the printer) |
| | | Optimized the threshold of clogging nozzles when the ink amount is low |
| | | Optimized the load threshold of the carriage motor |
| | | Changed the control settings for the maintenance unit motor |
| 06.31.TG22M7 | Function change | Set an individualized password for each unit |
| 06.31.TG08MB | Function change | The models have complied with the UK's PSTI bill. |
| | Bug fix | Fixed a bug caused by a false recognition of the Paper Top Position. |
| 06.31.TG09N2 | Bug fix | Fixed an empty space that was created on a boundary between pages when Banner Printing was performed. |
| 06.32.TG31N3 | Bug fix | Fixed a bug that occurred when connecting to Wi-Fi. (The fix was rolled out from other models.) |
| 06.32.TG19N5 | Bug fix | Fixed a problem (Memory Full) of an internal SD card. |
| | | Corrected a mis-description (Maintenance Error) in Korean on the LCD panel |
| 06.32.TG06N7 | Function change | Modified the paper stop position for fanfold paper in the same position as that of roll paper. |
| 06.32.TG31N8 | Function change | Changed the password, which resets the administrator password, to deal with the UK's PSTI bill. |
| 06.40.TG26N9 | Added new function | NiceLabel Cloud is supported. |
| | Bug fix | Fixed a bug that causes an error while Wi-Fi Direct is enabled. |
| 06.41.TG20NA | Bug fix | Detecting black marks on the glossy back of the paper is now available. |
| | | Fixed a bug that causes in WebConfig while NiceLabel Cloud is enabled. |
| 06.41.TG29O2 | Bug fix | Fixed a system error that occurred during printing. |
| 06.44.TG03OA | Function change | To improve the function [Change item] The guidance for the paper removal error [New] Improved |
| | | To improve the function [Change item] Default settings of the character encoding [New] Added |
| | | To improve the function [Change item] The setting items of the operation panel of the printer, PrinterSetting, and WebConfig. [New] Reconsidered options for "Actions on Power On" and "Actions when Replacing Media". |
| | | To improve the function [Change item] The color adjustment mode and the color correction [New] Added "Epson preferred color". |

| | | |
|--|--|--|
| | | <p>To improve the function [Change item] Gap detection [New] Added support for Kenko Label.</p> |
| | | <p>To improve the function [Change item] Improvement of the DNS name indication [New] Alphanumeric characters have been supported.</p> |
| | | <p>To improve the function [Change item] The default language of CW-C4040 for Korea [New] The default language has been changed to Korean from English.</p> |
| | | <p>To improve the function [Change item] The background color for barcodes and two-dimensional symbols [New] White color has been added to the background color as a replacement for the QuietZone function.</p> |
| | | <p>To improve the function [Change item] Enhancement of the print throughput [New] The animations on the operation panel screen of the printer have been enabled to turn on/off.</p> |
| | | <p>To improve the function [Change item] ERMS/PORT [New] Added ERMS/PORT as a supported function.</p> |
| | | <p>To improve the function [Change item] Error messages of Software Cloud [New] Improved</p> |
| | | <p>To improve the function [Change item] Icons on the operation panel of the printer [New] Changed the icons for paper feeding and amount of remaining paper.</p> |
| | | <p>To improve the function [Change item] WebConfig [New] Enhanced WebConfig as a common functionality for the ColorWorks series.</p> |
| | | <p>To improve the function [Change item] Ink discharging function</p> |

| | | |
|--------------|----------------------------------|---|
| | | [New] Added the ink discharging function for all colors. |
| | Bug fix | Fixed a bug where a designated font for the HRI characters cannot be printed when printing a CODE128 barcode. |
| | | Fixed a bug where the sound settings information does not display correctly with the EDA service. |
| 06.46.TG20P2 | Updated the supported OS version | Added support for Windows Server 2025. |
| | New function | [EPSON Cloud Solution PORT] Added the silent installation mode that executes the installation via WebConfig. |
| | Function change | The color correction method of ICM has been changed when using texture paper or plain paper. |
| | | Released the restriction of the ^FH command for multi-byte text print. |
| | | Released the restriction for drawing figures in low resolution. |
| | | Supported Enable/disable setting for TLS1.0/1.1. |
| | Bug fix | Fixed an issue with a missing count when replacing the new maintenance boxes. |
| | | Fixed an issue where the black ink density became high when matte ink was used. |
| | | Fixed an issue where Automatic restart could not be performed when the Wi-Fi was disconnected. |
| | | Fixed an issue that occurred a system error when a status sheet was printed from the operation panel. |