EPSON TM Bluetooth Connector

Version	Ver.2.04
Uploaded date	2019/8/26 9:00
File size	4,106KB
Explanation	This is a utility used to easily pair a terminal and a printer using Bluetooth. **[Note]** Updating OS causes deletion of Bluetooth pairing information stored in the OS, and user can no longer carry out printing. Therefore, after updating OS, use this tool again to pair user's terminal with a printer user wants to connect. **[Changes from Ver. 2.03 to Ver.2.04]** [Bug fix] Fixed a bug that an error may be recorded to Application in Windows Logs. [New support OS] - Added support for Windows 11 21H2 (64 bit) - Added support for Windows 10 21H2(32/64bit) [Added support models] Added support for the following models: TM-m30II, TM-m30II-H, TM-m30II-S, TM-m30II-SL, TM-m50, TM-m50II-H, TM-P20II, TM-P80II **[Support Model]** UB-B03, TM-H6000V, TM-P20, TM-P20II, TM-P60II, TM-P80, TM-P80II, TM-T88V, TM-T20II-m, TM-T70II, TM-T88VI, TM-m10, TM-m30, TM-m30II, TM-m30II-H, TM-m30II-S, TM-m30II-SL, TM-m30III, TM-m30III-H, TM-m50, TM-m50II-H, TM-L100 **[Support OS]** Windows 11 22H2 (64 bit) Windows 11 21H2 (64 bit) - Home, Pro, Enterprise Windows 10 22H2 (32/64 bit) Windows 10 21H2 (32/64 bit)(*) - Home, Pro, Enterprise, IoT Enterprise Windows 10 (32/64bit) Windows 8.1 (32/64bit) Windows 8 (32/64bit) Windows 7 SP1 (32/64bit) (*) It also supports Windows 10 21H2 in which the optional update (KB5014666) in June 2022 is applied. **[Interface]** Bluetooth **[Bluetooth Driver]** Built-in Bluetooth driver on Windows