# HVP Plug-in for EPSON GP-C83x

| | |
|---|---|
| Version | Ver.1.0.0.3 |
| Uploaded date | 2015/4/1 17:00 |
| File size | 889KB |
| Explanation | [Important Note]<br>This software is available only with the printers which have the mark on the nameplate label on the back of the TM-GP-C83x.<br>Please see the below "How to check Marking" file about the mark.<br>How to check marking<br>And this software is available for the product with the following firmware versions.The firmware version except:WAB10600,WAB20300,WAB20400<br>Also please read the following "Support firmware version" file about the firmware version the each driver supports.<br>Supported firmware version<br><br>[Support model]<br>GP-C830,GP-C831,GP-C832<br><br>[Support interface]<br>Ethernet<br><br>[Support OS]<br>Windows 10 (32/64bit)<br>Windows 8.1 (32/64bit)<br>Windows 8 (32/64bit)<br>Windows 7 SP1 (32bit/64bit)<br>Windows Server 2012 R2<br>Windows Server 2012<br>Windows Server 2008 R2 SP1<br>Windows Server 2008 SP2 (32bit/64bit)<br><br>[Restrictions]<br>If SAP EH&S WWI HVP System is not used, HVP plug-in for EPSON GP-C83x cannot be used.<br><br>For the information on the usage and installation, please refer to the HVP Plug-in Module User's Guide included in this package. |

The nameplate label attached on the back of the product

EPSON GP-C831 122

MODEL M285A
42V ⎓ 1.0A

SERIAL No. TEEF000000

SEIKO EPSON CORP.

c UL us
LISTED
I.T.E.
4Z82
E142680

NOM

MADE IN CHINA

EH

Mark