# Epson TM-H6000V Slip Paper Sensor Adjustment Tool

| | |
|---|---|
| Version | Ver.1.00a |
| Uploaded date | 2018/8/10 9:00 |
| File size | 940KB |
| Explanation | This tool is for adjusting the slip paper sensor of the TM-H6000V. Use this tool if the Slip LED lights up or blinks even though slip paper has been removed from the printer.<br><br>**[Changes from previous version]**<br>[New support OS]<br>- Added support for Windows 11 21H2 (64 bit)<br>- Added support for Windows 10 21H2(32/64bit)<br>- Added Windows Server 2022<br>- Added Windows Server 2019 as a support OS<br><br>**[Supported model]**<br>TM-H6000V<br><br>**[Supported OS]**<br>Windows 11 22H2 (64 bit)<br>Windows 11 21H2 (64 bit)<br>- Home, Pro, Enterprise<br>Windows 10 22H2 (32/64 bit)<br>Windows 10 21H2 (32/64 bit)(*)<br>- Home, Pro, Enterprise, IoT Enterprise<br>Windows 10 (32/64 bit)<br>Windows 8.1 (32/64 bit)<br>Windows 8 (32/64 bit)<br>Windows 7 SP1 (32/64 bit)<br>Windows Vista SP2 (32/64 bit)<br>Windows Server 2022 (64 bit)<br>Windows Server 2019<br>Windows Server 2016<br>Windows Server 2012 R2<br>Windows Server 2012<br>Windows Server 2008 R2 SP1<br>Windows Server 2008 SP2 (32/64 bit)<br>Windows Embedded Standard 7<br>Windows Embedded POSReady 7<br><br>(*) It also supports Windows 10 21H2 in which the optional update (KB5014666) in June 2022 is applied. |