EPSON Advanced Printer Driver for TM-L500A

Code	Ver.4.59E
Uploaded date	2023/11/01
File size	55,142KB
Explanation	In addition to ordinary Windows printer driver functions, this driver has controls specific to POS. **[Changed from Ver.4.58 to Ver.4.59]** [Note] - The software license agreement has changed. [New support OS] - Added support for Windows 11 21H2 (64 bit) - Added Windows Server 2022 [Bug fix] The following bungs are fixed: - Fixed a bug that, when the status was checked with Status API right after printing, it returned the Power-off status. - Fixed a bug that, at PC startup, the command responses from the printer may be processed incorrectly and therefore the printer remains unavailable. - Fixed a bung that, when receiving response data divided from the command, the StatusAPI may not notify the application correctly. **[Support Model]** TM-L500A **[Support OS]** Windows 11 22H2 (64 bit) Windows 11 21H2 (64 bit) - Home, Pro, Enterprise Windows 10 22H2 (32/64 bit) Windows 10 (32/64 bit) Windows 8.1 (32/64 bit) Windows 8 (32/64 bit) Windows 7 SP1 (32/64 bit) Windows Vista SP2 (32/64 bit) Windows XP SP3 (32 bit) Windows Server 2022 Windows Server 2019 Windows Server 2016 Windows Server 2012 R2 Windows Server 2012 Windows Server 2008 R2 SP1 Windows Server 2008 SP2 (32/64 bit) Windows Server 2003 R2 SP2 (32/64 bit) Windows Embedded Standard 7 (*1) Windows Embedded Standard 2009 (*1) Windows Embedded POSReady 7 Windows Embedded POSReady 2009 Windows Embedded for Point of Service (*1) Windows Embedded Enterprise (32/64 bit) (*1) Windows XP Embedded SP2 (*1) *1 There is a need to introduce the components necessary for operation of the driver. For details, please refer to the installation manual. **[Note]**

	Please use the same version of EPSON Advanced Printer Driver for each host when a network printer is shared among two or more hosts.