

Modification Patch for compatibility behavior at connecting TM successor models

Version	
Uploaded date	2013/7/2 9:00
File size	997KB
Explanation	<p>Modification Patch for compatibility behavior at connecting TM successor models</p> <p>It turned out that successor model does not work with current model driver. e.g.)TM-T70II does not work with TM-T70 driver.</p> <p>Target driver version and printers are as follows.</p> <p>[Target driver] APD Driver Ver4.00 to Ver4.04, Ver4.50 to Ver4.53 UPOS Driver: OPOS Ver2.68 to Ver2.70R3 OPOS.NET Ver1.11.20 to Ver1.12.6 JavaPOS for Windows Ver1.11.20W to Ver1.13.6W JavaPOS for Linux Ver1.13L to Ver1.13.2L</p> <p>[Target printer] - TM-T81II, TM-T82II, TM-T70II (and all successor models)</p> <p>Please apply this patch program When the problem that successor model does not work or Before replace with a target printer.</p> <p>[Support OS]</p> <ul style="list-style-type: none">- Windows 7 SP1 (32/64bit)- Windows Vista SP2 (32/64bit)- Windows XP SP3 (32bit)- Windows Server 2008 R2 SP1- Windows Server 2008 SP2 (32/64bit)- Windows Server 2003 R2 SP2 (32/64bit)- Windows Embedded Standard 7- Windows Embedded Standard 2009- Windows Embedded POS Ready 7- Windows Embedded POS Ready 2009- Windows Embedded for Point of Service- Windows Embedded Enterprise (32/64bit)- Windows XP Embedded SP2