

# TM-T20X Series (Serial/USB models) Firmware Updater

Code	Ver.10.04 ESC/POS
Uploaded date	2023/11/01
File size	10,348KB
Explanation	<p><b>1.Note</b> The software will update the printer's firmware. Depending on the usage environment, firmware update might cause a malfunction of the printer. Before updating the firmware, please confirm with the printer seller or SI and others if there is no problem to update it.</p> <p><b>2.Environment</b> <b>[Support OS]</b> - Windows 11 - Windows 10 (32/64 bit)</p> <p><b>[Support interface]</b> - Serial - USB2.0/3.0 (USB3.0 is supported in the environment for Windows8 or later)</p> <p><b>[Other requirements]</b> - Administrator account is required.</p> <p><b>3.Supported Products</b> <b>[Support Model]</b> - TM-T20X, TM-T20III, TM-T82X, TM-T82III, TM-T83III, TM-T81III, TM-T100</p> <p><b>4.Changes from the Current Version</b> <b>[Update of Support OS]</b> - Added support for Windows 11. - End of support for Windows 8 and Windows 8.1.</p> <p><b>[Note]</b> The software license agreement has changed.</p>

Firmware Change History for TM-T20X Series (Serial/USB models)

Version	Category	Detail
10.02 ESC/POS	Added new function	Added Japanese fonts below: - JIS (JISX0208-1990): 6879 characters - Special characters: 845 characters (see below): - JIS: 2D21h to 2D7Eh, 7921h to 7C7Eh - JIS: 8740h to 879DEh, ED40h to EEFC, FA40 to FC4Eh
	Changed function	Changed USB Device ID : MDL, CID
10.03 ESC/POS	Added new function	Added a function to switch the paper width to 58mm.
	Fixed bug	Fixed a bug that a recovery point cannot be restored with the "Restore&Delete" operation.
	Fixed bug	Fixed a bug that a CPU error occurred while printing graphic data via USB.
10.04 ESC/POS	Updated support model/OS	Added support for Windows 11.
		End of support for Windows 8 and Windows 8.1.