TM-C3510 Printer Driver

driver cannot be installed.

Version	Ver.2.6.0.2
Uploaded date	2023/10/20
File size	64Bit 44,517KB / 32Bit 43,202KB
Explanation	 1.Note This driver cannot read the BSF file output in the driver of the previous version. Please install the printer driver of this version, after uninstalling the already installed printer driver. * Please be sure to provide the information above to the users. 2.Environment [Support OS]
	- Windows 11 - Windows 10 (32/64 bit) - Windows 8.1 (32/64 bit) - Windows 8 (32/64 bit) - Windows Server 2022 - Windows Server 2019 - Windows Server 2016 - Windows Server 2012R2 - Windows Server 2012
	[Support interface] - USB2.0 - Wired LAN
	[Development environment] - Microsoft Visual Studio 2005 or later.
	[Other requirements] - Administrator account is required.
	3.Supported Products [Support Model] - TM-C3510 (Firmware WAD31000 or later, and WAM31000 or later)
	 4.Restrictions If you upgrade the OS while connecting to a printer that is in the power-on state, the user settings might be erased. Therefore, it is recommended to re-install the driver after the OS upgrade. In response to the end of Microsoft support for OSes (Windows 8, Windows 8.1, and Windows Server 2012 at present), we will end the support for those OSes at the time of the