

# EPSON Advanced Printer Driver 6 for TM-m30II

|               |   |
|---------------|---|
| Code          | Ver.6.07R1  |
| Uploaded date | 2023/11/01  |
| File size     | 30,426KB  |
| Explanation   | <p>In addition to ordinary Windows printer driver functions, this driver has controls specific to POS.</p> <p><b>[Note]</b><br/>This package is Windows Printer Driver for the TM printer.<br/>Please install "StatusAPI for EPSON Advanced Printer Driver 6", if you would like to use "StatusAPI".<br/>Please use the version listed below and install "StatusAPI for EPSON Advanced Printer Driver 6" on the PC, if you would like to use this software.</p> <ul style="list-style-type: none"><li>- EPSON Advanced Printer Driver 5 Ver. 5.09 or later</li><li>- EPSON Advanced Printer Driver 4 Ver. 4.56 or later</li><li>- EPSON OPOS ADK Ver. 2.68 or later</li><li>- EPSON OPOS ADK for .NET Ver. 1.11.20 or later</li><li>- EPSON JavaPOS ADK Ver. 1.11.20 or later</li><li>- EpsonNet Simple Viewer Ver. 2.30 or later</li><li>- TM Virtual Port Driver Ver. 7.10a or later</li></ul> <p><b>[Changes from Ver.6.04 to Ver.6.07R1]</b></p> <ul style="list-style-type: none"><li>- Added support for models that comply with the UK's PSTI bill.</li><li>- The software license agreement has changed.</li></ul> <p><b>[Support Models]</b><br/>TM-m30II, TM-m30II-H, TM-m30II-NT, TM-m30II-S, TM-m30II-SL</p> <p><b>[Support OS]</b><br/>Windows 11 22H2 (64 bit)<br/>Windows 11 21H2 (64 bit)<br/>- Home, Pro, Enterprise<br/>Windows 10 22H2 (32/64 bit)<br/>Windows 10 (32/64 bit)<br/>Windows 8.1 (32/64 bit)<br/>Windows 8 (32/64 bit)<br/>Windows 7 SP1 (32/64 bit) (*2)<br/>Windows Server 2022 (64 bit)<br/>Windows Server 2019<br/>Windows Server 2016<br/>Windows Server 2012 R2<br/>Windows Server 2012<br/>Windows Server 2008 R2 SP1<br/>Windows Server 2008 SP2 (32/64 bit)<br/>Windows Embedded 8.1 Industry<br/>Windows Embedded Standard 7 (*1)<br/>Windows Embedded POSReady 7<br/>(*1) It is required to implement the components to operate the driver.<br/>(*2) Windows 7 security patches must be applied.</p> |