

# EPSON Advanced Printer Driver for TM-T20III L

Version	Ver.6.04
Uploaded date	2021/6/9 9:00
File size	14,944KB
Explanation	<p>In addition to ordinary Windows printer driver functions, this driver has controls specific to POS.</p> <p><b>[Note]</b></p> <ul style="list-style-type: none"><li>- This package is Windows Printer Driver for the TM printer.</li><li>- Please install "StatusAPI for EPSON Advanced Printer Driver 6", if you would like to use "StatusAPI".</li><li>-&gt; <a href="#">Link to "StatusAPI for EPSON Advanced Printer Driver 6"</a></li><li>- Please use the version listed below and install "StatusAPI for EPSON Advanced Printer Driver 6" on the PC, if you would like to use this software.<ul style="list-style-type: none"><li>EPSON Advanced Printer Driver 5 Ver5.09 or later</li><li>EPSON Advanced Printer Driver 4 Ver4.56 or later</li><li>EPSON OPOS ADK Ver2.68 or later</li><li>EPSON OPOS ADK for .NET Ver1.11.20 or later</li><li>EPSON JavaPOS ADK Ver1.11.20 or later</li><li>EpsonNet Simple Viewer Ver2.30 or later</li><li>TM Virtual Port Driver Ver7.10a or later</li></ul></li></ul> <p>If you would like to use the Sample Program for EPSON Advanced Printer Driver, please download "EPSON Advanced Printer Driver Version 6 Sample Program".</p> <p>-&gt; <a href="#">Link to "EPSON Advanced Printer Driver Version 6 Sample Program"</a></p> <p><b>[Changes from Ver.6.01 to Ver.6.04]</b></p> <p>[New support OS]</p> <ul style="list-style-type: none"><li>- Added support for Windows 11 21H2 (64 bit)</li><li>- Added support for Windows 10 21H2(32/64bit)</li><li>- Added Windows Server 2022</li></ul> <p>[Bug fix]</p> <ul style="list-style-type: none"><li>- Fixed an issue that it may not be able to print to the maximum printing width when printing half-width characters in multilingual fonts in an application created with Visual Basic 6.0.</li></ul> <p><b>[Support Models]</b></p> <p>TM-T20III L</p> <p><b>[Support OS]</b></p> <p>Windows 11 21H2 (64 bit)</p> <ul style="list-style-type: none"><li>- Home, Pro, Enterprise</li></ul> <p>Windows 10 21H2 (32/64 bit)(*)</p> <ul style="list-style-type: none"><li>- Home, Pro, Enterprise, IoT Enterprise</li></ul> <p>Windows 10 (32/64 bit)</p> <p>Windows 8.1 (32/64 bit)</p> <p>Windows 8 (32/64 bit)</p> <p>Windows 7 SP1 (32/64 bit)</p> <p>Windows Server 2022 (64 bit)</p> <p>Windows Server 2019</p> <p>Windows Server 2016</p> <p>Windows Server 2012 R2</p> <p>Windows Server 2012</p> <p>Windows Server 2008 R2 SP1</p> <p>Windows Server 2008 SP2 (32/64 bit)</p> <p>Windows Embedded 8.1 Industry</p> <p>Windows Embedded Standard 7 (*1)</p> <p>Windows Embedded POSReady 7</p> <p>(*) It also supports Windows 10 21H2 in which the optional update (KB5014666) in June 2022 is applied.</p> <p>(*1)It is required to implement the components to operate the driver.</p> <p><b>[Support I/F]</b></p> <p>Serial</p> <p>Parallel</p> <p>USB2.0/3.0 (USB3.0 is supported in the environment for Windows 8 or later)</p>

Wired/Wireless LAN  
Bluetooth

**[Development environment]**  
Microsoft Visual Studio 2005 or later