

EPSON JavaPOS ADK (for Windows OS)

Version	Ver.1.14.37W
Uploaded date	2025/2/17
File size	162,208KB
Explanation	<p>1.Note</p> <ul style="list-style-type: none">- Unzip the "Epson_JavaPOS_ADK_11437.zip" files. When you execute "Epson_JavaPOS_11437.exe", it automatically extracts the files to a specified folder for installation. The Installation guide "InstallerManual.pdf" is stored to the same folder. If you do not use SetupPOS, unzip the "EPSON_JavaPOS_ADK_11437_x86.zip" or "EPSON_JavaPOS_ADK_11437_x64.zip" files. When you execute batch file for install, it extracts the files to a specified folder for installation. Refer to the "EPSON JavaPOS ADK Installation Guide for Windows.txt" for details. <p>2.Environment</p> <p>[Support OS]</p> <ul style="list-style-type: none">Windows 11<ul style="list-style-type: none">- Windows 11 Pro, Windows 11 EnterpriseWindows 10 (32/64 bit)<ul style="list-style-type: none">- Windows 10 Pro, Windows 10 EnterpriseWindows 8.1 (32/64 bit)<ul style="list-style-type: none">- Windows 8.1, Windows 8.1 Pro, Windows 8.1 EnterpriseWindows 8 (32/64 bit)<ul style="list-style-type: none">- Windows 8, Windows 8 Pro, Windows 8 EnterpriseWindows 7 SP1 (32/64 bit)<ul style="list-style-type: none">- Professional, Ultimate, EnterpriseWindows Vista SP2 (32/64 bit)<ul style="list-style-type: none">- Business, Ultimate, EnterpriseWindows Server 2022<ul style="list-style-type: none">- Standard, Essentials, DatacenterWindows Server 2019<ul style="list-style-type: none">- Standard, Essentials, DatacenterWindows Server 2016<ul style="list-style-type: none">- Standard, Essentials, DatacenterWindows Server 2012 R2<ul style="list-style-type: none">- Standard, Essentials, DatacenterWindows Server 2012<ul style="list-style-type: none">- Standard, Essentials, DatacenterWindows Server 2008 R2 SP1<ul style="list-style-type: none">- Standard, Enterprise, DatacenterWindows Server 2008 SP2 (32/64 bit)<ul style="list-style-type: none">- Standard, Enterprise, DatacenterWindows Embedded Standard 7 (*1)Windows Embedded Standard 2009 (Full component) <p>[Support interface]</p> <ul style="list-style-type: none">- Serial- USB- Wired/Wireless LAN- Bluetooth <p>[Development environment]</p> <ul style="list-style-type: none">- Java<ul style="list-style-type: none">Java SE Development Kit 8 Update 101 (Oracle) or laterJava 11Java 17Java 21- JAI

Java Advanced Imaging 1.1.2

The Java Advanced Imaging package of Oracle is required when you use the Check Scanner.

[Other requirements]

- (*1) There is a need to introduce the following components necessary for operation of the driver.

[MUST components]

- Volume Shadow Copy Service : For printer driver Installation
- System Restore Core : For printer driver Installation
- OLE Dialog Interfaces : For printer driver Installation
- Task Scheduler : For USB driver Installation
- Primitive: DbgHelp : For USB driver Installation
- Local Printing Support : For using a printer driver

[Necessary components for each case]

- Communications Port: For using a printer driver, it is necessary to install this port manually if there is no serial or parallel port on a PC.
Please resolve dependency after these components are added.

3.Supported Products

[Support Model]

- EU-m30, TM-H2000, TM-H5000II, TM-H5200, TM-H6000II, TM-H6000III, TM-H6000IV, TM-H6000V, TM-H6000VI, TM-J2000, TM-J2100, TM-J7000, TM-J7100, TM-J7200, TM-J7500, TM-J7600, TM-J7700, TM-L90, TM-L90LinerFree, TM-L100, TM-m10, TM-m30, TM-m30II, TM-m30II-H, TM-m30II-NT, TM-m30II-S, TM-m30II-SL, TM-m30III, TM-m30III-H, TM-m50, TM-m50II, TM-m50II-H, TM-P20, TM-P20II, TM-P60, TM-P60II, TM-P60II Peeler, TM-P80, TM-P80II, TM-T20, TM-T20II, TM-T20III, TM-T20IIIL, TM-T20IV, TM-T20VI-SP, TM-T20IV-L, TM-T20X, TM-T20X-II, TM-T70, TM-T70II, TM-T81, TM-T81II, TM-T81III, TM-T82, TM-T82II, TM-T82III, TM-T82IIIL, TM-T82IV, TM-T82IV-L, TM-T82X, TM-T82X-II, TM-T83III, TM-T83IV, TM-T88III, TM-T88IV, TM-T88V, TM-T88VI, TM-T88VII, TM-T90, TM-T100, TM-U220, TM-U220II, TM-U230, TM-U950
- DM-D110, DM-D210, DM-D30, DM-D500, DM-D70

4.Changes from the Current Version

[Note]

- Added a digital signature to the binary files to comply with Windows 11 Smart App Control.

[Bug fix]

- After turning the power back on, it takes a long time before printing is possible due to the large number of nulls sent during the initialization process.