

# TM-T60 (USB model) Firmware Updater

Version	Ver.1.02 ESC/POS
Uploaded date	2019/12/9 9:00
File size	2,790KB
Explanation	<p>This software updates the TM-T60 (USB model) Firmware to Version 1.02 ESC/POS. Depending on the usage environment, the firmware update may cause the printer to malfunction. Consult with the printer seller, SI, or others in advance.</p> <p><b>[Changes from previous version]</b> Firmware Change History</p> <p><b>[Support Model]</b> TM-T60 (USB model)</p> <p><b>[Support OS]</b></p> <ul style="list-style-type: none"><li>- Windows 10 (32/64bit)</li><li>- Windows 8.1 (32/64bit)</li><li>- Windows 8 (32/64bit)</li><li>- Windows 7 SP1 (32/64bit)</li><li>- Windows Vista SP2 (32/64bit)</li></ul> <p><b>[Notes]</b> This firmware updater can be used only for TM-T60 (USB model).</p>

### Firmware Change History for TM-T60 (USB model)

Version	Category	Detail
1.02 ESC/POS		Measures to prevent missing dots caused by over energy.
	Changed function	Added support for a new flash ROM to deal with EOL of the current one.
	Bug fix	Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control.