

Epson Deployment Tool

Version	Ver.3.7.0
Uploaded date	2024/6/26
File size	23,124KB
Explanation	<p>This is a tool used to install a lot of printers efficiently and set the printer driver and change the settings of driver. Also with this tool, it can create a silent package easily to install or setting the driver.</p> <p>1.Note - None</p> <p>2.Environment [Support OS] - Windows 11 - Windows 10 (32/64bit) - Windows 8.1 (32/64bit) - Windows 8 (32/64bit) - Windows 7 SP1 (32/64 bit)</p> <p>[Support interface] - Serial - Parallel - USB2.0/3.0 (USB3.0 is supported in the environment for Windows 8 or later.) - Wired/Wireless LAN - Bluetooth</p> <p>[Other requirements] Printer Driver: - TM-C3500: Ver.1.0.0.5a or later - TM-C3510: Ver.1.0.0.1a or later - TM-C3520: Ver.1.0.0.1a or later - TM-C3400: Ver.1.4 or later - Advanced Printer Driver Ver.4.09 or later - Advanced Printer Driver Ver.5.00 or later - CW-C6000/C6500 series Printer Driver Ver. 1.0.0.0 or later - CW-C8000 series Printer Driver Ver. 1.0.0.0 or later</p> <p>EpsonNet SetupManager Ver.2.2.2 or later TM-XX utility (Only for supported products)</p> <p>(*) The Advanced Printer Driver is not necessary if you are using UPOS driver.</p> <p>(*) In the UPOS driver environment, you can set the printer by using the EPSON Deployment Tool; however, you cannot set the UPOS driver.</p> <p>3.Supported Products [Support Model] - BA-T500II - CW-C6000 series, CW-C6500 series, CW-C8000 series - DM-D70 - EU-m30 - TM-C3400, TM-C3400BK, TM-C3500, TM-C3510, TM-C3520 - TM-H2000, TM-H6000IV, TM-H6000V, TM-H6000VI - TM-J7200, TM-J7700, TM-L500A Ticket, TM-L90, TM-L100 - TM-m10, TM-m30, TM-m30II, TM-m30II-H, TM-m30II-S, TM-m30II-SL, TM-m30II-NT, TM-m30III, TM-m30III-H, TM-m50, TM-m50II, TM-m50II-H - TM-P20, TM-P60II, TM-P80, TM-P20II, TM-P80II</p>

- TM-S2000MJ, TM-S9000MJ, TM-S2000II-MJ, TM-S9000II-MJ, TM-S2000II-NW, TM-S9000II-NW
- TM-T20, TM-T20II, TM-T20III, TM-T20IIIL, TM-T20X, TM-T70II, TM-T70II-DT2, TM-T81, TM-T81II, TM-T81III
- TM-T82, TM-T82II, TM-T82III, TM-T82IIIL, TM-T82X, TM-T83III, TM-T88V, TM-T88VI, TM-T88VII, TM-T88VI-DT2
- TM-T88VI-iHUB, TM-T100

4. Changes from the Previous Version

[Added support for the following models]

- TM-H6000VI

[Bug fix]

- None